Accurate Inspections Inc. Property Inspection Report



1221 N. Harvest Walk Dr, La Puente CA, 91555 Inspection prepared for: John Felix & Jan Felix Agent: Jane Smith - Smith Realty

Inspection Date: 8/1/2007 Time: 3:30 to 5:45 Weather: Sunny

Inspector: Mike Verlingo

Report Summary

Attic	-			
Page 3 Item: 5	Exhaust Vent	Several of the bathroom exhaust pipes terminate in the attic. This can cause a buildup of moisture and eventually mold in the attic.		
Electrical				
Page 9 Item: 1	Electrical Panel	There was evidence of water within the panel., I reccommend having a licensed electrician evaluate., 14 gauge wire runs to a 30 amp breaker, improper electrical installation, Undersized wires to a breaker.		
Page 10 Item: 7	Main Gas Valve Condition	No seismic shut off present., I recommend having the Gas Company evaluate the valve.		
Garage	-			
Page 16 Item: 13	Fire Door	The fire door from the garage to the kitchen did not self close and latch		
Grounds				
Page 20 Item: 13	Sprinklers	Visible leaking of sprinker valves.		
Heating				
Page 21 Item: 1	Heater Condition	The unit does not have proper clearence. The walls to it's side are too close		
Page 22 Item: 7	Filters	Filters were dirty. I recommend replacing the filters to ensure proper function of the heating system		
Interior	-			
Page 25 Item: 14	Smoke Detectors	Two of the interior smoke detectors did not operate.		
Kitchen				
Page 27 Item: 4	Dishwasher	Some water discharged out of the air gap during operation.		
Page 27 Item: 5	Doors	The door did not have a latch to the exterior.		
Page 28 Item: 17	Spray Wand	The spray was irregular, it should be replaced.		
Waterheater	T			
Page 35 Item: 3	Water Heater Condition	Evidence of leaking was seen on the water heater base.		
Page 36 Item: 7	Plumbing	The water heater shut off handle was missing. This should be repaired by a licensed plumber.		

Attic								
1. Access								
Fair	Poor	N/A	None	Observations: The attic was accesible through the master bedroom closet.				



Attic Access

Attic view

2. Chimney

Good	Fair	Poor	N/A	None	Observations: The home does not have a chimney.
			Х		

3. Duct Work

Good	Fair	Poor	N/A	N
X				

Observations: The duct work appeared functional. For a thorough inspection I recommend an evaluation by a Heating & A/C contractor.



Attic Duct Work

Attic Duct Work

4. Electrical
Good Fair Poor N/A None X Image: Second Seco
5. Exhaust Vent Good Fair Poor N/A None Observations: The exhaust vent was functional. X Several of the bathroom exhaust pipes terminate in the attic. This can cause a
X Several of the bathroom exhaust pipes terminate in the attic. This can cause a buildup of moisture and eventually mold in the attic.
6. Insulation Condition
Good Fair Poor N/A None X A A A A Materials: fiberglass batts Materials: 6, inches
7. Attic Plumbing
Good Fair Poor N/A None Observations: Most of the plumbing was not accessible due to insulation.
8. Structure
Good Fair Poor N/A None Observations: Truss type roofing present
9. Ventilation
Good Fair Poor N/A None Observations: There is proper ventilation in the attic.
10. Vent Screens
X Fair Poor N/A None Observations: All the vent screens in the attic are present and in good condition.

Bathrooms can consist of many features from jacuzzi tubs and showers to toilets and bidets. Because of all the plumbing involved it is an important area of the house to look over. Moisture in the air and leaks can cause mildew, walpaper and paint to peel, and other problems. The home inspector will identify as many issues as possible but some problems may be undetectable due to problems within the walls or under the flooring..

Bathroom
1. Locations
Materials: Master#1, Hall#2
2. Cabinets
Good Fair Poor N/A None Observations: All cabinets in the home are fully functional.
3. Ceiling Condition
Good Fair Poor N/A None Materials: drywall
4. Counters
Good Fair Poor N/A None Observations: The counters had some normal wear and tear.
5. Doors Good Fair Poor N/A None Observations: All doors in the home are fully functional.
6. Electrical
Good Fair Poor N/A None
7. GFCI
Good Fair Poor N/A None Observations: The GFCI tested and operated properly.
8. Exhaust Fan
Good Fair Poor N/A None Observations: The exahaust fan operated normally.

9. Floor Condition
Good Fair Poor N/A None Materials: carpet, tile
X Observations: The carpets were worn and stained in several areas.
10. Heating
Good Fair Poor N/A None Observations: Heating is controlled via central unit. Please see the Heating &
Air Conditioning page.
11. Mirrors
Good Fair Poor N/A None Observations: Bathroom mirrors were fully functional. No chipping or fading
X was found.
12. Plumbing
Good Fair Poor N/A None
13. Security Bars
Good Fair Poor N/A None
14. Showers
Good Fair Poor NA None Observations: The shower, including the drain and all its hardware is fully
X functional.
15. Shower Walls
Good Fair Poor N/A None Observations: The shower walls showed normal wear due to slight moisture.
X
16. Bath Tubs
Good Fair Poor N/A None Observations: The tub showed normal wear.
X
17. Enclosure
Good Fair Poor N/A None Observations: The enclosure consisted of a curtain.

18. Sinks
Good Fair Poor N/A None X Image: Second state Image: Second state Second state Second state
19. Toilets
Good Fair Poor N/A None Observations: The toilet had worn hardware.
20. Wall Condition
Good Fair Poor N/A None Materials: drywall
X
21 Window Condition

ZI .	VVIIIC		COLIC	annor	
Good	Fair	Poor	N/A	None	Materials: aluminum
Х					Observations: The hall window is missing.
					All other windows are functional.

The main area of inspection in the bedrooms is the structural system. This means that all walls, ceilings and floors will be inspected. Doors and windows will also be investigated for damage and normal operation. Personal items in the bedroom may prevent all areas to be inspected as the inspector will not move personal items.

Bedroom
1. Locations
Materials: Master, South#2, North#3
2. Bar
Good Fair Poor N/A None
3. Cabinets
Good Fair Poor N/A None
4. Ceiling Condition
Good Fair Poor N/A None Materials: drvwall
5. Ceiling Fans Good Fair Poor N/A None
6. Closets
Good Fair Poor N/A None Observations: The closets are fully functional.
7. Doors
Good Fair Poor N/A None Observations: The doors are fully functional.
8. Electrical
Good Fair Poor N/A None X Image: Some of the outlets in the bedroom were not accessable. All other outlets were functional.

9. Fireplace
Good Fair Poor N/A None
10. Floor Condition
Good Fair Poor N/A None Materials: carpet
X Observations: The bedroom floors were stained and worn.
11. Security Bars
Good Fair Poor N/A None
12. Sliding Doors Good Fair Poor N/A None
13. Screen Doors
Good Fair Poor N/A None
14. Smoke Detectors
Good Fair Poor N/A None Observations: The smoke detector operated properly.
15. Wall Condition
Good Fair Poor N/A None Materials: drywall
X Observations: Some areas of the wall were not accessable due to personal
items.
16. Window-Wall AC or Heat
Good Fair Poor N/A None
17. Window Condition
Good Fair Poor N/A None Materials: aluminum
X Observations: All bedroom windows were functional.

					Electrical		
1. Electrical Panel							
Good	Fair	Poor	N/A	None	⊓Materials: Main Location: , east side		
Х					Observations: Undersized wires to a breaker., There was evidence of water		
					within the panel., I reccommend having a licensed electrician evaluate., 14		

gauge wire runs to a 30 amp breaker, improper electrical installation, Undersized wires to a breaker.



Electrical Panel

Electrical Sub Panel

2. Main Amp Breaker

Good	Fair	Poor	N/A	None	Observations: 100 amp
Х					

3. Breakers in off position
Good Fair Poor N/A None X Image: N/A Image: N/A Image: N/A Image: N/A X Image: N/A Image: N/A Image: N/A Image: N/A
4. Breakers
Good Fair Poor N/A None X Image: N/A Materials: copper Observations: All breakers were functional.
5. Fuses
Good Fair Poor N/A None
6. Cable Feeds

 $\frac{Good}{K}$ Fair Poor N/A None Observations: Electrical cable feeds were located underground.

7. Main Gas Valve Condition

Good	Fair	Poor	N/A	Materials: east side
X				Observations: Main gas into the house is natural gas., No seismic shut off
				present., I recommend having the Gas Company evaluate the valve.
				present., rrecommend naving the Cas company evaluate the valve.



Main Gas Valve

Exterior
1. Doors
Good Fair Poor N/A None X Image
2. Eaves & Facia
Good Fair Poor N/A None Observations: The facia had several small cracks., Boards appeared to be weathered.
3. Exterior Paint
Good Fair Poor N/A None X Image: Second seco
4. Siding Condition
Good Fair Poor N/A None
5. Stucco
Good Fair Poor N/A None Observations: Stains and small cracks were found.,
6. Window Condition
Good Fair Poor N/A None X Image: Source of the second seco

Foundation
1. Slab Foundation
Good Fair Poor N/A None Observations: Part of the slab not visible due to floor coverings.
2. Foundation Perimeter
Good Fair Poor N/A None Observations: The foundation perimeter is partially visible.
3. Ventilation
Good Fair Poor N/A None Image:
4. Vent Screens
Good Fair Poor N/A None
5. Access Panel Good Fair Poor N/A None
6. Post and Girders
Good Fair Poor N/A None

Foundation view

Foundation view

1221 N. Harvest Walk Dr, La Puente

7. Sub Flooring
Good Fair Poor N/A None
8. Foundation Walls
Good Fair Poor N/A None
9. Cripple Walls
Good Fair Poor N/A None
10. Anchor Bolts
Good Fair Poor N/A None Observations: No anchor bolts were visible.
11. Chimney Hearth Good Fair Poor N/A None
12. Foundation Electrical
12. Foundation Electrical Good Fair Poor N/A None X
12. Foundation Electrical Good Fair Poor NA None X X X
12. Foundation Electrical Good Fair Poor N/A None X

Exposed electrical connections. Missing junction box cover.



Foundation Plumbing

14. I	Duct	ing		
Good	Fair	Poor	N/A	None
				X

Garage
1. Cabinets
Good Fair Poor N/A None
2. Counters
Good Fair Poor N/A None
3. Electrical
Good Fair Poor N/A None X
4. GFCI
Good Fair Poor N/A None X Image Image Image Image Image X Image Image Image Image Image Image X Image Image Image Image Image Image Image X Image Image Image Image Image Image Image X Image
5. 220 Volt
Good Fair Poor N/A None Observations: A 220 volt socket could not be found.
6. Flooring Condition
Good Fair Poor N/A None X
7. Garage Door Condition
Good Fair Poor N/A None Materials: sectional door X Observations: Garage door functions normally.
8. Garage Door Parts
Good Fair Poor N/A None Observations: functional
9. Garage Opener Status
Good Fair Poor N/A None X Image: Solution of the second se

10. Garage Door's Reverse Status
Good Fair Poor N/A None Observations: operated, eye beam system present
11. Roof Condition
Good Fair Poor N/A None Materials: same as the main structure
12. Exterior Door
X Observations: Garage exterior doors were functional
13. Fire Door
Cood Fair Poor NA None Observations: The fire door from the garage to the kitchen did not self close and latch
14. Rafters & Ceiling
Good Fair Poor N/A None Observations: Garage rafters were not designed for heavy storage.
15. Wash Basin
Good Fair Poor N/A None
16. Walls
Good Fair Poor N/A None
17. Anchor Bolts
Observations: Anchor bolts were not accesible.
18. Vent Screens
Good Fair Poor N/A None Observations: Vent screens were functional. No holes were seen.

19. \	Winc	lows		
Good	Fair	Poor	N/A	None
				X

Grounds
1. Driveway and Walkway Condition
Good Fair Poor N/A None X A A A A Observations: There are quite a few oil stains on the driveway. There were small cracks in the driveway. The sidewalk was elevated in several places which is a trip hazard.
2. Patio and Porch Condition
Good Fair Poor N/A None X A B
3. Balcony
Good Fair Poor N/A None
4. Patio Enclosure
Good Fair Poor N/A None
5. Patio and Porch Deck
X Fair Poor N/A None Observations: Small cracks were seen on the porch. X I I I I I I I I I I I I I I I I I I I
6. Stairs & Handrail
Good Fair Poor N/A None
7. Grounds Electrical
Good Fair Poor N/A X



Missing wire nuts

8. G	FCI				
Good X	Fair	Poor	N/A	None	Observations: The GFCI was tested and operated normally. The reset switch for the GFCI is located in the garage.

9. Fence Condition
Good Fair Poor N/A None X A A A A Observations: Some weathering was noticed on the fence. There is contact between the earth and wood. This can cause termite problems. The fence could not be fully inspected due to plant growth.
10. Gate Condition

Goo	d Fa	ir	Poor	N/A	None	Materials: wood
X						Observations: The gate was fully functional.
-						The hardware was a bit old and worn.

11.	Grac	ding			
Good	Fair	Poor	N/A	None	$_1$ Observations: No drains were visible in the area.
X	Х				Signs of poor drainage were present.
					The grading was elevated in several places which is a trip hazard.

12. Plumbing										
Good	Fair	Poor	N/A	None	ר Materials: copper					
X										

13. Sprinklers
Good Fair Poor N/A None X The system was tested and worked. Visible leaking of sprinker valves.
<image/>
14. Water Pressure Good Fair Poor N/A None Observations: 75, psi
15. Pressure Regulator
$\begin{array}{c c} \hline \textbf{S} \\ \hline \textbf{Good} \\ \hline \textbf{Fair} \\ \hline \textbf{Poor} \\ \hline \textbf{N/A} \\ \hline \textbf{None} \\ \hline \textbf{Observations: The pressure regular was present, but not tested.} \\ \hline \textbf{X} \\ \hline \textbf{X} \\ \hline \textbf{S} \\ \hline \textbf{X} \\ \hline \textbf{S} \hline \textbf{S} \hline \textbf{S} \\ \hline \textbf{S} \hline \textbf{S} \hline \textbf{S} \\ \hline \textbf{S} \hline \textbf{S} \\ \hline \textbf{S} \hline \textbf$
16. Water Shut-off Valve Condition
Good Fair Poor N/A None X Image Image Image

The heating, ventillation, and air conditioning and cooling system (often referred to as HVAC) is the climate control system for the structure. The goal of these systems is to keep the occupants at a comfortable level while maintaining indoor air quality, ventillation while keeping maintenance costs at a minimum. The HVAC system is usually powered by electricity and natural gas, but can also be powered by other sources such as butane, oil, propane, solar panels, or wood.

The inspector will usually test the heating and air conditioner using the thermostat or other controls. For a more thorough investigation of the system please contact a licensed HVAC service person.

Heating
1. Heater Condition
Good Fair Poor N/A None X Attended Materials: Location: , attic Materials: gas, forced, split system Observations: The water heater was functional. The unit does not have proper clearence. The walls to it's side are too close

Heater

Heating Heater Condition

2. Heater Base
Good Fair Poor N/A None
3. Enclosure
Good Fair Poor N/A None
4. Gas Valves
Good Fair Poor N/A None X Image: Source of the second seco

5. Thermostats
Good Fair Poor N/A None X Image: Second seco
6. Venting
Good Fair Poor N/A None Observations: The vent could not be fully inspected due to personal items in way
7. Filters
Good Fair Poor N/A None Observations: Filters were dirty. I recommend replacing the filters to ensure proper function of the heating system
8. Air Supply
Good Fair Poor N/A None Observations: The air supply was functional and in a good location
9. Registers
Good Fair Poor N/A None X Deservations: The air registers were functional
10. Refrigerant Lines
Good Fair Poor N/A None Observations: Refrigerant lines could not be fully inspected due to X I I I I I I I I I I I I I I I I I I
11. AC Compress Condition
Good Fair Poor N/A None Materials: electric
X Materials: patio area Observations: A/C Compressor operated at 49 degrees



Heating AC Compress Condition

The Interior section covers areas of the house that are not considered part of the Bathrooms, Bedrooms, Kitchen or areas covered elsewhere in the report. Interior areas usually consist of hallways, foyer, and other open areas. Within these areas the inspector is performing a visual inspection and will report visible damage, wear and tear, and moisture problems if seen. Personal items in the structure may prevent the inspector from viewing all areas on the interior.

The insector does not usually test for mold or other hazardous materials. A qualified expert should be consulted if you would like further testing.

Interior
1. Bar
Good Fair Poor N/A None
2. Cabinets
Good Fair Poor N/A None Observations: All cabinets were functional.
3. Ceiling Fans
Good Fair Poor N/A None
4. Ceiling Condition
Good Fair Poor N/A None Materials: drywall
5. Closets
Good Fair Poor N/A None Observations: The closets were functional.
6. Door Bell
Good Fair Poor N/A None Observations: The door bell operated normally.
7. Doors
Good Fair Poor N/A None X Image: Second Seco

8. Electrical Good Fair Poor N/A None Observations: Some of the outlets in the interior were not accessible.
9. Fireplace Good Fair Poor N/A None Materials: Living Room X Materials: prefabricated Observations: The fireplace is gas only.
10. Floor Condition
Good Pair Poor N/A None X A A A A Observations: The interior carpeting and tile is stained and worn.
11. Security Bars Good Fair Poor N/A None X
12. Sliding Doors Good Fair Poor N/A None Good Fair Poor N/A None X X X X
13. Screen Doors Good Fair Poor N/A None
14. Smoke Detectors
15. Stairs & Handrail Good Fair Poor N/A None X
16. Wall Condition
X A None Materials: drywall Observations: Some areas of the wall were not visible due to personal items.

17. Window-Wall AC or Heat

Good	Fair	Poor	N/A	None
				Х

18. Window Condition

Good	Fair	Poor	N/A	None	Materials: aluminum, stationary
Х					Observations: The interior windows are functional.
~					

Kitchen
1. Cabinets
Good Fair Poor N/A None Observations: All kitchen cabinets were functional, and had no missing hardware.
2. Ceiling Condition
Good Fair Poor N/A None Materials: drywall
3. Counters
Good Fair Poor N/A None Observations: There was normal wear on the tile counters.
4. Dishwasher
Good Fair Poor N/A None Observations: The dishwater operated. X Some water discharged out of the air gap during operation.
5 Deere
5. Doors Good Fair Poor N/A None X
6. Electrical
6. Electrical $\frac{Good}{Fair}$ Poor N/A None Observations: Some of the kitchen outlets were not accessible due to appliances.
7. GFCI
Good Fair Poor N/A None Observations: The GFCI tested operational.
8. Floor Condition
Good Fair Poor N/A None X Image: Algorithm of the second sec

9. Garbage Disposal
10. Microwave Good Fair Poor N/A None Image: Construction of the second se
11. Cook top condition Good Fair Poor N/A None X Image: Source of the second sec
12. Oven & Range Good Fair Poor N/A None X Image: N/A Observations: The gas oven was operational.
13. Plumbing Good Fair Poor N/A None X I I I I I I I I I I I I I I I I I I I
14. Security Bars Good Fair Poor N/A None X
15. Sinks Good Fair Poor N/A None Observations: The sinks were functional. The fixtures and the surface of the sink were worn. Rust was found on the sink fixtures. There were several chips in the sink itself.
16. Drinking Fountain Good Fair Poor N/A None X Image: State of the state of t
17. Spray Wand Good Fair Poor N/A None Observations: The spray wand operated. X The spray was irregular, it should be replaced.

18. Hot Water Dispenser Good Fair Poor N/A None Good Fair Poor N/A None X X X X
19. Soap Dispenser Good Fair Poor N/A None Image: Construction of the second seco
Sliding Doors Good Fair Poor N/A None L L X
Screen Doors Good Fair Poor N/A None Image: Colspan="3">Image: Colspan="3" Good Fair Poor N/A None Image: Colspan="3">Image: Colspan="3" Image: Colspan="3">Image: Colspan="3" Image: Colspan="3">Image: Colspan="3" Image: Colspan="3">Image: Colspan="3" Image: Colspan="3">Image: Colspan="3" Image: Colspa
22. Trash Compactor Good Fair Poor N/A None Good Fair Poor N/A None X X X X
23. Vent Condition Good Fair Poor N/A None X Image: Self Self Self Self Self Self Self Self
24. Wall Condition Good Fair Poor N/A None X NA None Materials: drywall
25. Window Condition

		Fair	Poor	N/A	None	Materials: aluminum
	Х					Observations: The windows were functional and in good condition.
L					1	

Accurate Inspections Inc.	1221 N. Harvest Walk Dr, La Puente
Laundry	
1. Locations	
Materials: In the garage area	
2. Cabinets Good Fair Poor N/A None	
3. Counters	
4. Ceiling Condition	
Materials: drywall	
5. Dryer Vent	
X None Observations: The dryer vent wa	s functional.
6. Electrical Good Fair Poor N/A None	
X	
7. GFCI Good Fair Poor N/A None	
8. Exhaust Fan Good Fair Poor N/A None	
9. Doors	
Good Fair Poor N/A None	

10. Floor Condition				
Good Fair Poor N/A None Materials: concrete				
11. Gas Valves				
Good Fair Poor N/A None X Image: Source of the second seco				
12. Plumbing				
Good Fair Poor N/A None Observations: The plumbing was not tested.				
13. Wall Condition				
Good Fair Poor N/A None Materials: drywall				
14. Wash Basin				
Good Fair Poor N/A None Image:				
15. Window Condition				
Good Fair Poor N/A None Image:				
16. Security Bars				
Good Fair Poor N/A None				

Pool
1. Air Booster Pump
Good Fair Poor N/A None
2. Deck Condition
Good Fair Poor N/A None
3. Electrical
Good Fair Poor N/A None
4. GFCI
Good Fair Poor N/A None Image:
5. Gate & Fence Condition
Good Fair Poor N/A None Image:
6. Filter
Good Fair Poor N/A None Image:
7. Skimmer and Basket
Good Fair Poor N/A None
8. Pool Heater Condition
Good Fair Poor N/A None
9. Lights
Good Fair Poor N/A None

Good Fair Poor N/A None Image: Image of the state
Good Fair Poor N/A None
12. Jets Good Fair Poor N/A None
Good Fair Poor N/A None
Good Fair Poor N/A None Image: Constraint of the second sec
15. Timer Good Fair Poor N/A None
16. Water Condition Good Fair Poor N/A None Image: State of the stat
Good Fair Poor N/A None Image: Source of the second

Roof						
1. Roof Condition						
Good Fair Poor N/A None Materials: tile X Image: State of the state of						
2. Chimney						
Good Fair Poor N/A None Observations: The chimney was accessible due to type of roofing material The chimeney was inspected from the ground only.						
3. Flashing						
Good Fair Poor N/A None Observations: The flashing was not accessible.						
4. Gutter						
Good Fair Poor NA None Observations: There were no rain gutters attached to the roof.						
5. Sky Lights						
Good Fair Poor N/A None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None Image: None <t< td=""></t<>						
6. Spark Arrestor						
Good Fair Poor N/A None Observations: The spark arrestor was present. Could not access due to A height						
7. Vent Caps						
Good Fair Poor N/A None Observations: The vent caps were functional.						

Waterheater
1. Base
Good Fair Poor N/A None Observations: Water heater base has moisture present.
2. Combusion
Good Fair Poor N/A None Observations: Combustion operated normally.
3. Water Heater Condition
Good Fair Poor N/A None Materials: gas X None Materials: gas Materials: garage Observations: Water heater operated normally., Evidence of leaking was seen on the water heater base.
Water Hoster
Water Heater
4. Heater Enclosure
Good Fair Poor N/A None
5. Gas Valve Good Fair Poor N/A None Observations: The gas valve operated normally.
6. Overflow Condition
Good Fair Poor N/A None X Image: A starting of the

7. Plumbing			
Good Fair Poor N/A None X A A A A Observations: Insulation was present around the plumbing The water heater shut off handle was missing. This should be repaired by a licensed plumber.			
8. Strapping			
Good Fair Poor N/A None			
9. TPRV			
Good Fair Poor N/A None Observations: TPRV functioned normally.			
10. Venting			
Good Fair Poor N/A None X Image: Second			
Improper installation of vent pipe. Exhaust vent from water heating in the basement area.			

11. Number of Gallons

Materials: 40 gallons

Photos



Exterior Electrical Panel

Residential Earthquake Hazards Report				
Yes	No	N/A	Don't Know	
Х				1. Is the water heater braced, strapped, or anchored to resist falling during an earthquake?
Yes	No	N/A	Don't Know	
Х				2. Is the house anchored or bolted to the foundation?
Yes	No	N/A	Don't Know	3. If the house has cripple walls:
		Х		a. Are the exterior cripple walls braced?
Yes	No	N/A	Don't Know	, but the outerior formulation consists of uncomposited concrete sizes and
		Х		b. If the exterior foundation consists of unconnected concrete piers and posts, have they been strengthened?
Yes	No	N/A	Don't Know	
		Х		4. If the exterior foundation, or part of it, is made of unreinforced masonry, has it been strengthened?
Yes	No	N/A	Don't Know	5. If the house is built on a hillside: a. Are the exterior tall foundation walls braced?
		Х		
Yes	No	N/A	Don't Know	
		Х		b. Were the tall posts or columns either built to resist earthquakes or have they been strengthened?
Yes	No	N/A	Don't Know	
		Х		6. If the exterior walls of the house, or part of them, are made of unreinforced masonry, have they been strengthened?
Yes	No	N/A	Don't Know	
		Х		7. If the house has a living area over the garage, was the wall around the garage dooropening either built to resist earthquakes or has it been strengthened?
Yes	No		Don't	
Χ			Know	3. Is the house outside an Alquist-Priolo Earthquake Fault Zone (zones immediately surrounding known earthquake faults)?
Yes	No		Don't Know	
Χ				9. Is the house outside a Seismic Hazard Zone (zone identified as susceptible to liquefication or landsliding)?
EXECUTED BY:				
(Selle	er)			(Seller) Date
I acknowledge receipt of this form, completed and signed by the seller. I understand that if the seller has answered "No" to one or more questions, or if seller has indicated a lack of knowledge, there may be one or more earthquake weaknesses in this house.				

(Buyer)

Date